;

Flush Task	44702	
Location		
Locator Address: 5630 23rd St N	Asset: Non-Asset	
Entered Address: 5630 23rd ST N	Intersecting Street:	
Details		
Status: Completed	Department: DES - WSS - SM	
Activity: Flush	Activity Feature Type:	
Priority: None	Emergency: No	
Dates		
Estimated Start Date: 06/26/2017 - 12:00 AM	Estimated Stop Date: 06/26/2017 - 12:00 AM	
Actual Start Date: 06/26/2017 - 12:00 AM	Actual Stop Date: 06/26/2017 - 09:27 AM	
Links		
Request:	Work Order:	
Entry		
Entry Date: 06/26/2017 - 09:24 AM	Entered By: kowalker	
Notes		

Arrived at location 5630 N.23rd St., STOPPAGE CALL OVER THE WEEKEND, ROCKS IN SEGMENTS. Opening MH#14281 flushed and vacuum to 4590 =115ft., 5 times, to remove Rocks and debris.--41/SE--

Printed: 10/04/2017 - 05:16 PM

Page: 1

Flush Task	44825
Location	
Locator Address: 5630 23rd St N	Asset: Non-Asset
Entered Address: 5630 23rd ST N	Intersecting Street:
Details	
Status: Completed	Department: DES - WSS - SM
Activity: Flush	Activity Feature Type:
Priority: None	Emergency: No
Dates	
Estimated Start Date: 06/26/2017 - 12:00 AM	Estimated Stop Date: 06/26/2017 - 12:00 AM
Actual Start Date: 06/26/2017 - 12:00 AM	Actual Stop Date: 06/26/2017 - 12:15 PM
Links	
Request:	Work Order:
Entry	
Entry Date: 06/26/2017 - 11:24 AM	Entered By: kowalker
Notes	

Stoppage call on the weekend at 5630 N. 23rd St. (5805). ((5724)Arrived at location open MH#4588 flushed and vacuum segment with small cleaning nozzle to MH#4587=144ft., 10 times to remove rocks and debris from main for TV INSPECTION.--41/SE--

Printed: 10/05/2017 - 05:34 AM

Page: 1